



MONA LIFTING

PEIRIANNEG OFFER CODI - LIFTING GEAR ENGINEERING

Lifting Machines and Accessories Report

- *Lifting Operations & Lifting Equipment Regulations 1998
- *Provision & Use of Work Equipment Regulations 1998
- *Regular Thorough Examination

NB. Under the Lifting Operations & Lifting Equipment Regulations 1998 Regulation 10 we have a statutory obligation to report any defective lifting equipment to the Health and Safety Executive where a defect is considered to be or could become a danger to persons and where there is an imminent risk of serious personal injury.

Name of User : M.A.D. Sound & Lighting
 Address : Unit 1 Llwyn Onn Industrial Estate, Amlwch,
 Anglesey LL68 9BH

Sales Order Report No: SO 8333

Order Number : Verbal
 Colour Code : -

Page Number : 1 of 20

Location of equipment when examination and tests carried out: Mona Showground, Gwalchmai, Anglesey.

Where equipment or systems contain electronic or electrical devices, the inspection (as with previous inspections) does not extend to an assessment of whether the plant, or any part of it is year 2000 compliant within the meaning of the BSI definition DISC PD 2000.

Competent Person

Date of commencement of examination and tests : 2nd March 2010

Mona Lifting Ltd
 Llwyn Ednyfed
 Llangedfni, Ynys Mon LL77 7SE

Date of report : 2nd March 2010

Telephone : 01248 751300

Engineer Surveyor

: 

Fax : 01248 751304

A L Thomas

A: Examination Dates.

B: Particulars sufficient to uniquely identify the equipment or identification number. Make and year of manufacture.

C: Safe Working Load / Working Load Limit.

D: Defect which could cause danger to persons. Particulars of any repairs, renewals or alterations to rectify and the time in which those defects shall be rectified.

Identification of any other part found to be deteriorating and which requires rectifying.
 Observations and recommendations.

A. Examination Dates.	B. Identifying Number.	C. SWL / WLL	D. Defects Found.
Last : 04/02/09 Current : - Next : ASAP	Pfaff Hook Suspension Chain Block. Model 0867013. Height of lift 9m. Single fall. Year of manufacture 2000. Identification No. 129371742.	2t	Unable to locate on site at time of inspection.
Last : 04/02/09 Current : 02/03/10 Next : 02/03/11	Pfaff Hook Suspension Chain Block. Model 0867013. Height of lift 9m. Single fall. Year of manufacture 2000. Identification No. 129371735.	2t	Identification number requires stamping but otherwise serviceable.

Lifting Machines and Accessories Report

Report No. : SO 8333

Page : 2 of 20

A. Examination Dates.	B. Identifying Number.	C. SWL / WLL	D. Defects Found.
Last : 04/02/09 Current : - Next : ASAP	Pfaff Hook Suspension Chain Block. Model 0867013. Height of lift 9m. Single fall. Year of manufacture 2000. Identification No. 129371747.	2t	Unable to locate on site at time of inspection.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000574349.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000546712.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000763666.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000763667.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000763663.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000574348.	1t	None - Serviceable.

Date of report : 2nd March 2010

Engineer Surveyor : 
A L Thomas

Lifting Machines and Accessories Report

Report No. : SO 8333

Page : 3 of 20

A. Examination Dates.	B. Identifying Number.	C. SWL / WLL	D. Defects Found.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 3m. Year of manufacture 1999. Identification No. 000573206.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2000. Identification No. 000763659.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2000. Identification No. 000763661.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Stage Platform Frame. Identification No. 4007.	500 kgs	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2000. Identification No. 000763658.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 1999. Identification No. 000596925.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2000. Identification No. 000763656.	1t	None - Serviceable.

Date of report : 2nd March 2010

Engineer Surveyor : 
A L Thomas

Lifting Machines and Accessories Report

Report No. : SO 8333

Page : 4 of 20

A. Examination Dates.	B. Identifying Number.	C. SWL / WLL	D. Defects Found.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2000. Identification No. 000763657.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Stage Platform Frame. Identification No. 4006.	500 kgs	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/03/11	Pfaff Hook Suspension Chain Block Model 0867013. Height of lift 9m. Single fall. Year of manufacture 2000. Identification No. 129371748.	2t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2005. Identification No. 001344094.	2t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2005. Identification No. 001344096.	2t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2005. Identification No. 001304180.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2005. Identification No. 001304183.	1t	None - Serviceable.

Date of report : 2nd March 2010


Engineer Surveyor : 
A Thomas

Lifting Machines and Accessories Report

Report No. : SO 8333

Page : 5 of 20

A. Examination Dates.	B. Identifying Number.	C. SWL / WLL	D. Defects Found.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2005. Identification No. 001304181.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 2m. Year of manufacture 2005. Identification No. 001304185.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 1m. Year of manufacture 1999. Identification No. 000600952.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	Duplex Webbing Sling. Length 1m. Year of manufacture 1999. Identification No. 000600948.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	3/4" dia. Large D Shackle with type A pin. Identification No. W6.4.	2t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	3/4" dia. Large D Shackle with type A pin. Identification No. W6.7.	2t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.2.	2t	Requires individual identification number stamping but otherwise serviceable.


Date of report : 2nd March 2010
 Engineer Surveyor : 
A L Thomas

Lifting Machines and Accessories Report

Report No. : SO 8333

Page : 6 of 20

A. Examination Dates.	B. Identifying Number.	C. SWL / WLL	D. Defects Found.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.4.	1t	Requires individual identification number stamping but otherwise serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.5.	1t	Requires individual identification number stamping but otherwise serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.6.	1t	Requires individual identification number stamping but otherwise serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.7.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.10.	1t	None - Serviceable.
Last : 04/02/09 Current : 02/03/10 Next : 02/09/10	1/2" dia. Small D Shackle with type A pin. Identification No. P52.12.	1t	None - Serviceable.
Last : 04/02/09 Current : - Next : ASAP	1/2" dia. Small D Shackle with type A pin. Identification No. P52.18.	1t	Unable to locate on site at time of inspection.

Date of report : 2nd March 2010
 Engineer Surveyor : 
A L Thomas